


MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 17, Township 10 North, Range 1 West,

Monument Description & Remarks: 1" Iron Pipe found flush with ground




COMPLETED By *Steve Farkes*

I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 27th day of December, 2004 A.D.

Ben E Bledsoe

Indiana Registered Land Surveyor No. S0559



CORNER I.D.


MONUMENT RECORD

I-11

STATE OF INDIANA - COUNTY OF MONROE

SECTION 17, TOWNSHIP 10 N, RANGE 1E ^{1W}MONUMENT DESCRIPTION & REMARKS ¹⁻³⁻⁹¹FOUND 1" IRON PIPE 1" OUT OF GROUND

RECOVERY TIE DRAWING



(●) AT CORNER



NOT TO SCALE

STATE OF INDIANA

COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS 17 TH DAY OF DECEMBER, 19 90 A.D.

SPACE
RESERVED
FOR
RECORDING
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. _____

OR _____

UNITED STATES GOVERNMENT AGENCY

TOWNSHIP:
BENTON

CORNER I.D.

TITLE _____